FLIGHT SOURCE INTERNATIONAL, INC.



Worldwide Aircraft Sales and Acquisitions sales@flightsource.com Sarasota, Florida, USA Nassau, Bahamas Phone: +1 941.355.9585 / Fax: +1 941.296.7442

1997 HAWKER 800XP

Serial Number 258319 Registration OD-TSW



AIRFRAME: 6524 Total Hours

3608 Cycles

ENGINES: TFE731-5BR-1H

6434 Hours Total Time

Left Serial Number P107188

3662 Landings

4200 TBO, 2100 M.P.I. Intervals Right Serial Number P107183 6348 Hours Total Time 3558 Cycles

Both Engines to be overhaul as per manufacturer recommendations and requirements.

APU: Honeywell GTCP 36-150WSerial Number: P312**To be overhauled as per manufacturer recommendations and requirements.**

Located at Genel Havacilik Maintenance Facility, Istanbul, Turkey

This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale

FLIGHT SOURCE INTERNATIONAL, INC.



Worldwide Aircraft Sales and Acquisitions sales@flightsource.com Sarasota, Florida, USA Nassau, Bahamas Phone: +1 941.355.9585 / Fax: +1 941.296.7442

AVIONICS:


AHRS: Dual Honeywell AHZ-600 Autopilot: Honeywell DFZ-800 AFCS EFIS: Honeywell EDZ-818 2-tube FDR: Fairchild F-1000 FMS: Dual Honeywell NZ-2000 w/6.0A software Hi Frequency: Dual King KHF-950 w/Coltech SELCAL Radar Altimeter: Honeywell AA-300 TAWS: Honeywell Mark VII EGPWS w/windshear Weather Radar: Honeywell Primus 880 AFIS: Global AFIS Comms: Dual Honeywell RCZ-851 CVR: Universal CVR-30 Flight Director: Honeywell DFZ-800 AFCS Flight Phone: MagnaStar C-2000 GPS: Dual Honeywell (12-channel) Stormscope: Honeywell LSZ-850 TCAS: Honeywell TCAS-II w/change 7 Navs: Dual Honeywell RNZ-850



ADDITIONAL: Honeywell Digital N1 DEEC's W/ECTM, Honeywell MDZ-818 Multi-Function Display, Dual Honeywell RM-850 Radio Management Units, Dual Honeywell ADZ-810 Air Data Computers, Safe Flight Angle Of Attack, Dual Honeywell AV-850A Audio Systems, Honeywell CD-820 CDU's, Honeywell RAAS, Baker M1050 Audio System, Artex C406N ELT W/Nav Interface, Honeywell Flight ID, Honeywell Elementary Surveillance, J.E.T. Standby Horizon, Davtron Digital Clock, Granger Static Discharge System, Lee Aerospace Single-Panel Cabin Windows, Long-Range Oxygen, Lo-Presti Boom Beam Wing & Taxi, Whelen High-Intensity Strobes, Devore Tel-Tail Logo, Precise Pulselites



INTERIOR: Complete Refurbishment Underway in Executive Eight Passenger Seating with Four Executive Seats, 2-Place Divan, Forward Custom Galley, Forward Baggage Area, Belted Aft Lav



EXTERIOR: Complete Repaint to Include Stripping, Corrosion Treatment - Colors per Buyers Choice

MAINTENANCE: Currently, the aircraft is in maintenance and the estimated RTS date is not advised yet Work package includes performing the below tasks to return the aircraft to an airworthy condition.:

- Routine and Non-routine tasks.
- E, F, G, and all Due Calendar month checks.
- Replacing all expired life-limited parts.
- Conducting all applicable AD's and SB's.
- Engines and APU overhaul as per manufacturer recommendations and requirements.
- Landing gear Overhaul
- Exterior stripping, corrosion treatment and painting.
- Interior Refurbishment.
- ADS-B out upgrade.
- Additional requirements are recommended by TEXTRON Aviation.
- ENGINES, AVIONICS and APU enrollment in Honeywell MSP coverage program
- Enrollment in CAMP System

AVAILABLE IMMEDIATELY, Call Maria +1 941-586-2054 maria@flightsource.com