



FLIGHT SOURCE
INTERNATIONAL, INC.

FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

maria@flightsource.com

8100 15th Street East.

Sarasota, FL 34243, USA

Phone: 941.355.9585 / Fax: 941.296.7442

1984 Westwind II

Serial Number 410

Registration N772DC



Airframe:

7368 Hours Since New

6164 Landings

Engine: Honeywell TFE 731-3-1G

Left: Serial Number P77570

618 Hours Since CZI

MSP Gold 4200 TBO

Right Serial Number P77574

618 Hours Since CZI

Avionics:

ADF: Collins ADF-60

Flight Director: Dual Collins FDS-85

Radar Altimeter: Collins ALT-55B

Transponder: Dual Honeywell MST-67A Mode S

Comms: Dual Collins VHF-20B

FMS: Garmin 750

TCAS: Honeywell CAS-67A TCAS-II w/change 7

Artex ELT-200

CVR: Fairchild G 100

IFCS High Frequency: Collins HF-230

TAWS: Bendix/ King-560 Class B

Autopilot: Collins APS-80 IFCS

DME: Dual Collins DME-40

Navs: Dual Collins VIR-30A

Weather Radar: Collins WXR-300 color

SATCOM



FLIGHT SOURCE
INTERNATIONAL, INC.

FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

maria@flightsource.com

8100 15th Street East.

Sarasota, FL 34243, USA

Phone: 941.355.9585 / Fax: 941.296.7442



Maintenance: RVSM, on CAMS, Always U.S. Registered

| Inspection | Interval | Last Done | Next Due | Remain |
|-----------------------------|-----------------|------------------|-----------------|---------------|
| Aircraft "A" Check | 200 hrs. | 7247.9 | 7447.9 | 82 |
| Aircraft "B" Check | 400 hrs. | 7247.9 | 7647.9 | 282 |
| Aircraft "C" Check | 800 hrs. | 6861.9 | 7661.9 | 296 |
| 200 Flight Hours | 200 hrs. | 7247.9 | 7447.9 | 82 |
| Airframe Structural "A & B" | 4800 hrs. | 4500.3 | 9300.3 | 1934.4 |
| Airframe Structural "B" | 800 hrs. | 6861.9 | 7661.9 | 296 |
| Structural "C" Initial | 9600 hrs. | | 9600 | 2234.1 |
| Structural "C" Recurrent | 4800 hrs. | | Not Due | Not Due |
| Structural "D" Inspection | 15000hrs | | 15000 | 7634.1 |

Exterior:

Overall White with Carter Gold Stripes. Repainted in 2005.

AVAILABLE IMMEDIATELY, MAKE OFFER, CONTACT MARIA OR ERIC ECKARDT

Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale.



FLIGHT SOURCE
INTERNATIONAL, INC.

FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

maria@flightsource.com

8100 15th Street East.

Sarasota, FL 34243, USA

Phone: 941.355.9585 / Fax: 941.296.7442



Interior:

Executive Seven Passenger with Beige Leather Seating, Forward RS Side-Facing Seat, LS Single Aft-Facing Seat, Single Forward-Facing Seat & Aft Club Refreshment Equipment: Forward Galley Entertainment Equipment: In-Flight Cabin Display, CD/DVD Player, Three 7-Inch LCD Displays, Wireless Headphones & Speakers, Flushing Lav with Vanity.



Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale.