



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442

1981 LEARJET 35A

Serial Number 402

Registration N35BG



AIRFRAME:

12,011 Hours Since New

12,169 Landings

ENGINES: TPE731-2-2B

Left: Serial Number P89124C

31,304 Hours Total Time

28,149 Cycles

3415 hours since overhaul

MSP Gold 4200TBO

Right: Serial Number P89129C

22,924 Hours Total Time

20,833 Cycles

3445 hours since overhaul

ADDITIONAL: ZR Lite package, Raisbeck Aft Locker, Eros Oxygen Masks, Engine Sync, Davtron Clock, FED 2000 Windshield Defoggers, Thrust Reversers Aeronica



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442

AVIONICS: ADS-B

ADF: Collins ADF-60

Altimeter: IDC System II encoding w/RAD/BAR

Comms: Dual Collins VHF-20A

DME: Dual Collins DME-42

FMS: Universal UNS-1C+

Navs: Dual Collins VIR-30A

RMI: Dual Allen AAR-3137

Weather Radar: Honeywell Primus 400

406 ELT

GPS: Garmin 400

Autopilot: J.E.T. FC-200

CVR: Fairchild GA100

Flight Director: Dual Collins FIS-84

Hi Frequency: King KHF-950

Radar Altimeter: Collins ALT-50

TCAS

Transponder: Mode S



INTERIOR: Executive Eight Passenger Leather Seating, 3 Place Aft Couch, 2 Club Aft Facing Chairs, 1 Mid Cabin Forward Facing Chair, Mid Cabin Refreshment Center. Current Configuration has Forward Storage Box with Unbelted Seat, Aft Facing Chair Can Be Installed, Belted Lavatory

This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442



EXTERIOR: Matterhorn White Upper Half, Maxi Blue Lower Half with Phantom Gray Accent Stripes, Repaint 1/19

MAINTENANCE: FAR 135, 12,000 Hours / 12 years c/w 10/18, MEDEVAC Compliant, All Mandatory SB complied, Complete logs since New, No Known Damage History

Available Immediately, Make Offer, Call: Eric Eckardt +1 941-586-6345 eric@flightsource.com



FLIGHT SOURCE
INTERNATIONAL, INC.

FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442



This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale